

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

1 / 14




Fig. 1

~~(S-3-1-0)~~

2/14

<del>Gang</del> (gear)	<del>geschlossene Schalvelemente</del> (closed shifting elements)				
	A	B	C	D	E
1	●			●	
2	●		●		
3	●	●			
4	●				●
5		●			●
6			●		●
R		●		●	

Fig. 2